

Printout of prices from the TEILE.PL web side

Number	902-10 Wiring harness for bumper	Year	Cond.	RRP Euro	Disc.	Price Euro
99661295401	Repair kit - ABS harness, RR	98-05	used	98.76	50%	49.39

Number	902-10 Wiring harness, passenger compartment	Year	Cond.	RRP Euro	Disc.	Price Euro
99661295700	ABS harness, repair kit, C4/TURBO, L	98-05	new	98.76	10%	88.88
99661295800	ABS harness, repair kit, C4/TURBO, R	98-05	new	98.76	10%	88.88
99662231315	Harness, front, L	02-05	new	407.92	10%	367.13
99662231200	Harness, headlight, Turbo, R	01	new	407.92	10%	367.13
99662231300	Harness, headlights, Turbo, L	01	new	407.92	10%	367.13
99661296000	Wiring harness ABS, repair kit, FL	02-05	new	98.76	10%	88.88
99661295100	Wiring harness ABS, repair kit, FL with PSM	02-05	new	81.57	10%	73.42